

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/15/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S0100_024MH

Test ID: D1032-022032

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S0100_009MH
0			Water Level	
107.4000015			General Observation	NEW MH
136.6999969	01	02	Broken Soil Visible	
184.8999939	10		Tap Factory	From 4512 Clifton
185.1000061			Dye Test Visible	@ TF - cleanout
185.1000061			Dye Test Not Visible	@ TF - downspout
185.1000061			Manhole	S0100_024MH
210			End of Survey	DYE TESTS COMPLETED